Unique Id: 009E2379-F4FCB220-1	C02A1
' Copyright 1999 Compaq Comput	er Corporation. All rights reserved
SOURCE: Compaq Computer Co	orporation INFORMATION BLITZ
INFORMATION BLITZ TITLE:	
Two DTSS Time Provider	Radio Models Have a Y2K Problem
DATE: 02-DEC-1999 INFORMATION BLITZ #: TD 272	28-CR
AUTHOR: Bob Wheater TEL#: 978-275-5400 EMAIL: Wheater@canth.lkg.d DEPARTMENT: DECnet/DTSS Eng	
PRODUCT NAME(S) IMPACTED:	DECdts DECnet/OSI V6.1/V6.2/V6.3 DECnet-Plus V7.1
PRODUCT FAMILY(IES):	PRODUCT NUMBERS:
Storage Systems Networks PC Software Other (specify)	
INTRODUCTION:	
	MOPF and GC-1000 radio model time providers due to their use of two digit year fields.
PROBLEM:	
	S\$PROVIDER.C, to read the time provided receivers has a year 2000 problem for

[TD 2728-CR] Two DTSS Time Provider Radio Models Have a Y2K Problem - BLITZ

This fix is NOT in DECnet/Plus V7.1 DTSS\$PROVIDER.C dated 9-DEC-1992

dated 30-OCT-1998.

This program was shipped in DECnet/OSI V6.1/V6.2/V6.3 and DECnet-Plus V7.1. This was corrected in DECnet-Plus V7.2/V7.2-1 DTSS\$PROVIDER.C

If the DTSS\$PROVIDER.C is dated prior to 6-AUG-1997, then 2 of the Time Provider Radio Models have a 2 digit year;

Heath Company Model GC-1000 Radio Receiver (WWV) and the Hopf Electronics Receiver Model 6020

RESOLUTION:

The Heath Company no longer manufactures the heath kit radio receivers, so it is apparent that the hardware has not been tested for Y2K issues. If you need more information about this issue consult the manufacturer (http://www.heathkit.com/tech.html). However, we show the software modifications required for the GC-1000 below.

There is new firmware for the HOPF clock which should be obtained from the manufacturer HOPF Elektronik GmbH (consult: http://www.hopf-time.com).

The software changes for the HOPF clock are shown below.

The DTSS\$PROVIDER.C can be modified and built as follows (the plus sign in the left hand column indicates the new code that was added - remove the plus sign before compiling):

Y2K fix for the GC1000 in DTSS\$PROVIDER.C in routine CvtTPtoUTC:

```
. . .
   /*
    * convert all fields in record
    * /
   if ( sscanf( TPdata, "%d:%d:%d.%d %d/%d/%d",
            &time.tm hour, &time.tm min, &time.tm sec, &tns,
            &time.tm mon, &time.tm mday, &time.tm year ) == EOF )
     (void) fprintf(stderr, "M GC1000: time/date field conversion failed\n");
     return(0);
     * fix year 2000 wraparound
     * /
     if (time.tm year < 90)
       time.tm year += 100;
     * convert tenths of seconds (hundreds of ms) into ns
     * /
______
```

Y2K fix for HOPF clock in DTSS\$PROVIDER.C in routine CvtHOPFtoUTC()

· · · /*

ADDITIONAL COMMENTS:

The lastest DCE ECOkits, ALPDCE04_014 and VAX DCE03_014 have the fix in DCE\$DTS PROVIDER HOPF.EXE.

The other 3 Time Providers in the sample program always used the Y2K conversion or use an offset from 1986. The 3 providers that were not affected are the following:

Precision Standard Time Inc. Model OEM-10 (WWV)

Spectracom Synchronized Clock Model 8170 (WWVB)

Traconex Integrated Time Source Model 1020 (WWV)

```
<>UPDATE /TEXT_UPDATE/UNIQUE_IDENTIFIER="009E2379-F4FCB220-1C02A1"-
    /TITLE="[TD 2728-CR] Two DTSS Time Provider Radio Models Have a Y2K Problem - BLITZ"
    /BADGE=(AUTHOR="999997", ENTER="913696", MODIFY="913696", -
    EDITORIAL_REVIEW="913696", TECHNICAL_REVIEW="999997") -
    /NAME=(AUTHOR="WHEATER BOB", ENTER="SPAINHOWER JOE", -
    MODIFY="SPAINHOWER JOE", EDITORIAL_REVIEW="SPAINHOWER JOE", TECHNICAL_REVIEW="WHEATER    /DATE=(AUTHOR=" 6-DEC-1999", ENTER=" 6-DEC-1999", -
```

```
EXPIRE=" 6-DEC-2001", FLASH=" 6-DEC-1999", MODIFY=" 7-DEC-1999", -
EDITORIAL_REVIEW=" 6-DEC-1999", TECHNICAL_REVIEW=" 6-DEC-1999") -
/GEOGRAPHY="USA"/SITE="EIRS"/OWNER="TIM-BLITZ"-
/FLAGS=(USA_CUSTOMER_READABLE, NOPOST_MESSAGE_DISPLAY, NOLOCAL, -
EUR_CUSTOMER_READABLE, GIA_CUSTOMER_READABLE, NOINIT_MESSAGE_DISPLAY, -
EDITORIAL_REVIEWED, FIELD_READABLE, FLASH, TECHNICAL_REVIEWED, READY)
```