



# Sun Fire™ B10n Content Load Balancing Blade Version 1.3 Product Notes

---

Sun Microsystems, Inc.  
[www.sun.com](http://www.sun.com)

Part No. 817-7170-10  
June 2004, Revision A

Submit comments about this document at: <http://www.sun.com/hwdocs/feedback>

Copyright 2004 Sun Microsystems, Inc., 4150 Network Circle, Santa Clara, California 95054, U.S.A. All rights reserved.

Sun Microsystems, Inc. has intellectual property rights relating to technology embodied in the product that is described in this document. In particular, and without limitation, these intellectual property rights may include one or more of the U.S. patents listed at <http://www.sun.com/patents> and one or more additional patents or pending patent applications in the U.S. and in other countries.

This document and the product to which it pertains are distributed under licenses restricting their use, copying, distribution, and decompilation. No part of the product or of this document may be reproduced in any form by any means without prior written authorization of Sun and its licensors, if any.

Third-party software, including font technology, is copyrighted and licensed from Sun suppliers.

Parts of the product may be derived from Berkeley BSD systems, licensed from the University of California. UNIX is a registered trademark in the U.S. and in other countries, exclusively licensed through X/Open Company, Ltd.

Sun, Sun Microsystems, the Sun logo, AnswerBook2, docs.sun.com, Sun Fire, and Solaris are trademarks or registered trademarks of Sun Microsystems, Inc. in the U.S. and in other countries.

All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. in the U.S. and in other countries. Products bearing SPARC trademarks are based upon an architecture developed by Sun Microsystems, Inc.

The OPEN LOOK and Sun™ Graphical User Interface was developed by Sun Microsystems, Inc. for its users and licensees. Sun acknowledges the pioneering efforts of Xerox in researching and developing the concept of visual or graphical user interfaces for the computer industry. Sun holds a non-exclusive license from Xerox to the Xerox Graphical User Interface, which license also covers Sun's licensees who implement OPEN LOOK GUIs and otherwise comply with Sun's written license agreements.

Use, duplication, or disclosure by the U.S. Government is subject to restrictions set forth in the Sun Microsystems, Inc. license agreements and as provided in DFARS 227.7202-1(a) and 227.7202-3(a) (1995), DFARS 252.227-7013(c)(1)(ii) (Oct. 1998), FAR 12.212(a) (1995), FAR 52.227-19, or FAR 52.227-14 (ALT III), as applicable.

DOCUMENTATION IS PROVIDED "AS IS" AND ALL EXPRESS OR IMPLIED CONDITIONS, REPRESENTATIONS AND WARRANTIES, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT, ARE DISCLAIMED, EXCEPT TO THE EXTENT THAT SUCH DISCLAIMERS ARE HELD TO BE LEGALLY INVALID.

---

Copyright 2004 Sun Microsystems, Inc., 4150 Network Circle, Santa Clara, California 95054, Etats-Unis. Tous droits réservés.

Sun Microsystems, Inc. a les droits de propriété intellectuelle relatant à la technologie incorporée dans le produit qui est décrit dans ce document. En particulier, et sans la limitation, ces droits de propriété intellectuelle peuvent inclure un ou plus des brevets américains énumérés à <http://www.sun.com/patents> et un ou les brevets plus supplémentaires ou les applications de brevet en attente dans les Etats-Unis et dans les autres pays.

Ce produit ou document est protégé par un copyright et distribué avec des licences qui en restreignent l'utilisation, la copie, la distribution, et la décompilation. Aucune partie de ce produit ou document ne peut être reproduite sous aucune forme, par quelque moyen que ce soit, sans l'autorisation préalable et écrite de Sun et de ses bailleurs de licence, s'il y en a.

Le logiciel détenu par des tiers, et qui comprend la technologie relative aux polices de caractères, est protégé par un copyright et licencié par des fournisseurs de Sun.

Des parties de ce produit pourront être dérivées des systèmes Berkeley BSD licenciés par l'Université de Californie. UNIX est une marque déposée aux Etats-Unis et dans d'autres pays et licenciée exclusivement par X/Open Company, Ltd.

Sun, Sun Microsystems, le logo Sun, AnswerBook2, docs.sun.com, Sun Fire, et Solaris sont des marques de fabrique ou des marques déposées de Sun Microsystems, Inc. aux Etats-Unis et dans d'autres pays.

Toutes les marques SPARC sont utilisées sous licence et sont des marques de fabrique ou des marques déposées de SPARC International, Inc. aux Etats-Unis et dans d'autres pays. Les produits portant les marques SPARC sont basés sur une architecture développée par Sun Microsystems, Inc.

L'interface d'utilisation graphique OPEN LOOK et Sun™ a été développée par Sun Microsystems, Inc. pour ses utilisateurs et licenciés. Sun reconnaît les efforts de pionniers de Xerox pour la recherche et le développement du concept des interfaces d'utilisation visuelle ou graphique pour l'industrie de l'informatique. Sun détient une licence non exclusive de Xerox sur l'interface d'utilisation graphique Xerox, cette licence couvrant également les licenciés de Sun qui mettent en place l'interface d'utilisation graphique OPEN LOOK et qui en outre se conforment aux licences écrites de Sun.

LA DOCUMENTATION EST FOURNIE "EN L'ÉTAT" ET TOUTES AUTRES CONDITIONS, DECLARATIONS ET GARANTIES EXPRESSES OU TACITES SONT FORMELLEMENT EXCLUES, DANS LA MESURE AUTORISEE PAR LA LOI APPLICABLE, Y COMPRIS NOTAMMENT TOUTE GARANTIE IMPLICITE RELATIVE A LA QUALITE MARCHANDE, A L'APTITUDE A UNE UTILISATION PARTICULIERE OU A L'ABSENCE DE CONTREFAÇON.

LA DOCUMENTATION EST FOURNIE "EN L'ÉTAT" ET TOUTES AUTRES CONDITIONS, DECLARATIONS ET GARANTIES EXPRESSES OU TACITES SONT FORMELLEMENT EXCLUES, DANS LA MESURE AUTORISEE PAR LA LOI APPLICABLE, Y COMPRIS NOTAMMENT TOUTE GARANTIE IMPLICITE RELATIVE A LA QUALITE MARCHANDE, A L'APTITUDE A UNE UTILISATION PARTICULIERE OU A L'ABSENCE DE CONTREFAÇON.



# Contents

---

Viewing the Latest Product Notes	1
Software Release Features	2
Key Features for Version 1.3.5	2
New Monitoring Features Supported in Version 1.3.5	3
New Features Introduced in Version 1.2 Update	5
VLANs Optional for SSL Proxy Blades	5
Hardware and Software Requirements	5
Updating the B1600 System Controller	7
▼ To Update the System Controller Firmware	8
Updating B10n Application Software and BSC Firmware	8
▼ To Update the B10n Application Software	9
▼ To Update the Software Non-interactively	11
▼ To Set the New Image to be the Default Image	12
▼ To Update the BSC Firmware	12
Replacing Your B10n Blade	13
▼ To Export the Configuration From the Old Board	13
▼ To Import the Configuration to the Upgraded Board	14
Updating Your Server	15
▼ To Update the SPARC Solaris Server Module	15

- ▼ To Update the x86 Solaris Server Module 16
- ▼ To Update the Linux Server Module 17
  - ▼ To Upgrade the Linux Server Module From an Existing Installation 17

## Known Issues 18

- Stopping Failover Monitoring or Unknown Failover State (Bug ID 5046437 and Bug ID 4925823) 18
- Stopping an Application Server While Running Application Monitoring (Bug ID 4997595) 19
- Unknown Filter Edge [b9000010] (Bug ID 4925821) 19
- VIP Address Conflict (Bug ID 4910001) 19
- Configuring VIP Addresses to be the Same as path failover Target IP Address (Bug ID 4907833) 20
- Layer 7 Based Services and Layer 4 Services With Rules Will Fail to Respond (Bug ID 4998054 and Bug ID 5060108) 20
- Removing Services (Bug ID 5057931) 20
- CRITICAL Message Displayed When Removing a Service (Bug ID 5057951) 21
- Rule Build Required Message (Bug ID 5057959) 21
- Rule Build Complete Message Appears Only on the Console (Bug ID 4879355) 21
- Message Indicates Configuration Change After Rebooting (Bug ID 5043929) 22
- Using the poweroff and poweron Commands (Bug ID 5028523) 22
- Using the app-monitor Configuration Command (Bug ID 4997604) 22
- Time Not Kept Consistent With System Controller (SC) (Bug ID 4946746) 22
- Incorrect MAC Address Overwritten Message (Bug ID 4925709) 23
- Diag Back-To-Back(External) LoopBack Test (Bug ID 4928957) 23
- Disabling All VLANs (Bug ID 4886383) 23
- Configuring Path-failover IP Addresses (Bug ID 4908470) 23
- Building Rules (Bug ID 4925705) 24

Error Messages for Updating the Bootrom Image (Bug ID 4926343)	24
Older Date Appears on config_1 and config_2 Files (Bug ID 4973992)	24
Application Monitor Commands (Bug ID 5003231)	24
SSL Traffic Without an SSL Device Cannot be Layer 7 Load Balanced (Bug ID 4950182)	24
IP Persistence Does Not Release Its Persistence With Short Timeouts (Bug ID 5023896)	25
Output From the show arp Command (Bug ID 4819914)	25
Online Help Documentation Error (Bug ID 4900728)	25
Specific Sequence Required	26
Adding an SSL Service With a Duplicate Port (Bug ID 4908515)	26
Skipping the Failover Synchronization at Boot Time	27
<code>config no ip interface 0 1</code>	27
Troubleshooting	27
VIP IDs Not Checked	27
commit Allowed Though No Changes	28
Server/SSL Does Not Respond to ping Even Though it is Marked as Up.	28



# Declaration of Conformity

Compliance Model Number: BP-4  
Product Family Name: Sun Fire B10n blade

## EMC

### USA—FCC Class A

This equipment complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

1. This equipment may not cause harmful interference.
2. This equipment must accept any interference that may cause undesired operation.

### European Union

This equipment complies with the following requirements of the EMC Directive 89/336/EEC:

*As Telecommunication Network Equipment (TNE) in Both Telecom Centers and Other Than Telecom Centers per (as applicable):*

EN300-386 V.1.3.1 (09-2001) Required Limits:

EN55022/CISPR22	Class A
EN61000-3-2	Pass
EN61000-3-3	Pass
EN61000-4-2	6 kV (Direct), 8 kV (Air)
EN61000-4-3	3 V/m 80-1000MHz, 10 V/m 800-960 MHz, and 1400-2000 MHz
EN61000-4-4	1 kV AC and DC Power Lines, 0.5 kV Signal Lines
EN61000-4-5	2 kV AC Line-Gnd, 1 kV AC Line-Line and Outdoor Signal Lines, 0.5 kV Indoor signal Lines > 10m
EN61000-4-6	3 V
EN61000-4-11	Pass

*As Information Technology Equipment (ITE) Class A per (as applicable):*

EN55022:1998/CISPR22:1997 Class A

EN55024:1998 Required Limits:

EN61000-4-2	4 kV (Direct), 8 kV (Air)
EN61000-4-3	3 V/m
EN61000-4-4	1 kV AC Power Lines, 0.5 kV Signal and DC Power Lines
EN61000-4-5	1 kV AC Line-Line and Outdoor Signal Lines, 2 kV AC Line-Gnd, 0.5 kV DC Power Lines
EN61000-4-6	3 V
EN61000-4-8	1 A/m
EN61000-4-11	Pass
EN61000-3-2:1995 + A1, A2, A14	Pass
EN61000-3-3:1995	Pass

**Safety:** This equipment complies with the following requirements of the Low Voltage Directive 73/23/EEC:

EC Type Examination Certificates:

EN60950:2000, 3rd Edition	TÜV Rheinland Certificate No. xxxxxxxxxxxx
IEC 60950:2000, 3rd Edition	CB Scheme Certificate No. xxxxxxxxxxxx
Evaluated to all CB Countries	
UL 60950, 3rd Edition, CSA C22.2 No. 60950-00	File: Vol. Sec.
UL 60950, 3rd Edition, CSA C22.2 No. 950-00	File: Vol. Sec.
FDA DHHS Accession Number (Monitors Only)	

**Supplementary Information:** This product was tested and complies with all the requirements for the CE Mark.

/S/

Dennis P. Symanski  
Manager, Compliance Engineering  
Sun Microsystems, Inc.  
4150 Network Circle, MPK15-102  
Santa Clara, CA 95054 U.S.A.  
Tel: 650-786-3255  
Fax: 650-786-3723

DATE

/S/

Pamela J. Dullaghan  
Quality Program Manager  
Sun Microsystems Scotland, Limited  
Springfield, Linlithgow  
West Lothian, EH49 7LR  
Scotland, United Kingdom  
Tel: +44 1 506 672 395 Fax: +44 1 506 670 011

DATE





# Sun Fire B10n Content Load Balancing Blade Version 1.3 Product Notes

---

This document contains important information about the Sun Fire™ B10n Content Load Balancing Blade Version 1.3.5 application software and the new server modules. This version includes all the features from Version 1.1, 1.2, 1.2 Update, and 1.3. The application software for this release is Version 1.3.5.

Refer to the latest issue of the Sun Fire™ Blade Application Journal for further configuration and architectural overview information. The Application Journal is available at:

<http://www.sun.com/products/networking/blades/index.html>

---

**Note** – The current Sun Fire B10n content load balancing blades are shipped with the Version 1.2 software. This document explains how to upgrade your software to the latest version.

---

**Note** – If you make configuration changes and the system is rebooted before entering `commit`, the configuration changes since the previous `commit` will be lost. Always enter the `commit` command after making configuration changes.

---

---

## Viewing the Latest Product Notes

Additional issues may arise after the publication of this version of the product notes. For the latest information, refer to the latest version of this document available at:

# Software Release Features

## Key Features for Version 1.3.5

Key Features for 1.3.5:

- Application monitoring through user scripts
- Weighted Least Connections load balancing scheme
- Response Time load balancing scheme

Software release 1.3.5 includes support for the following operating systems listed in TABLE 1.

**TABLE 1** Supported Servers and Operating Systems

Operating System	Version	SPARC/x86	SF B1600 Server Blades			External Server		VLANs
			SF B100s	SF B100x	SF B200x	SF V60/65x	SF V210/240	
Solaris	8 HW 12/02	SPARC	X				X	Yes
Solaris	8 HW 5/03	SPARC	X				X	Yes
Solaris	8 HW 7/03	SPARC	X				X	Yes
Solaris	8 HW 2/04	SPARC	X				X	Yes
Solaris	9 8/03	SPARC	X				X	Yes
Solaris	9 12/03	SPARC	X				X	Yes
Solaris	9 4/04	SPARC	X				X	Yes
Red Hat Enterprise Linux (RHEL)	AS 2.1	x86		X	X			No
Red Hat Enterprise Linux (RHEL)	AS 2.1 Update-2	x86		X	X	X		No
Red Hat Enterprise Linux (RHEL)	AS 3.0	x86		X	X	X		Yes

**TABLE 1** Supported Servers and Operating Systems

Operating System	Version	SPARC/x86	SF B1600 Server Blades			External Server		VLANs
			SF B100s	SF B100x	SF B200x	SF V60/65x	SF V210/240	
SuSe	SLES 8.0 SP-3	x86		X	X	X		Yes
x86 Solaris	9 8/03	x86		X	X	X		No
x86 Solaris	9 12/03	x86		X	X	X		No
x86 Solaris	9 4/04	x86		X	X	X		No

Zip files are available at the Sun Download Center at the following URL:  
<http://www.sun.com/software/download/network.html>

Enter **B10n** and select Search the Download Center. Select Sun Fire B10n Content Load Balancing. Zip files listed in TABLE 2 are available.

## New Monitoring Features Supported in Version 1.3.5

A new feature has been added that checks the configuration of the backend servers for the services offered on the load balancer periodically. The monitoring, which is based on ICMP PING messages, checks for the VIPs being configured on the loopback interface and the service VLANs being configured properly on the server and the switch. The result of this configuration check is shown in the `show service service_name` and `show service-lb-group service_name lb_grp_name` outputs on the CLI. In the case of a bad configuration, the Path column is marked as DN, otherwise it is marked UP for a server in a service.

In addition, a new column, Valid, has been added to the output for a server in a service. A server marked invalid is not being used for load balancing in that particular load balancing group. A server is valid only if all the following conditions are true:

1. The server status is UP. This is true if the module is loaded properly on the server, the interface on the server configured with the real IP is up and the management VLAN, if applicable, is configured properly on the load balancer, switch and server.
2. The server is enabled globally.
3. If application monitoring is enabled for the service, then the application must be up on the server.
4. The server is enabled in the service.
5. The configuration check on the server (as described above) passes.

The following provides sample outputs:

```
puma{admin}# show service-lb-group svcl default
*-----*-----*-----*-----*-----*-----*-----*
Server Group:
=====
Name                : default
Scheme              : wt-least-conn
Total and Active servers : 3 / 3
Rules in group      : 0

Group Server Table:
=====
Server Name          Port    Wt/CWt  Status    App    Conf Path Valid Conn/s
-----
--
10.4.128.152        0        1/18   UP/EN/ACT  UP/EN  Done  UP   Yes  1
10.4.128.151        0        1/14   UP/EN/ACT  UP/EN  Done  UP   Yes  1
10.4.128.150        0        1/14   UP/EN/ACT  UP/EN  Done  UP   Yes  1
=====
```

```
puma{admin}# show service-lb-group svcl rt-grp
*-----*-----*-----*-----*-----*-----*-----*
Server Group:
=====
Name                : rt-grp
Scheme              : response-time
Total and Active servers : 3 / 3
Rules in group      : 0

Group Server Table:
=====
Server Name          Port    Wt/CWt  Status    App    Conf Path Valid RT(ms)
-----
--
10.4.128.152        0        1/19   UP/EN/ACT  UP/EN  Done  DN   No   25
10.4.128.151        0        1/12   UP/EN/ACT  UP/EN  Done  UP   Yes  27
10.4.128.150        0        1/12   UP/EN/ACT  UP/EN  Done  UP   Yes  27
=====
```

# New Features Introduced in Version 1.2 Update

The Sun Fire B10n content load balancing blade application software release 1.1 adds high availability pair blade failover and path failover as well as support for the Sun Fire B10p SSL proxy blade.

**TABLE 2** Zip Files Available at the Sun Download Center

Software Components	Zip File Name
BSC firmware	SunFire_B10n-version#-BSCFirmware.zip
B10n application software	SunFire_B10n-version#-Application.zip
Blade server module	SunFire_B10n-version#-SolarisModule.zip SunFire_B10n-version#-LinuxModule.zip
Administration Guide and Product Notes	SunFire_B10n-version#-Docs.zip

---

## VLANs Optional for SSL Proxy Blades

The use of VLANs within the Sun Fire B1600 blade system is preferred when using the Sun Fire B10p SSL proxy blade. VLANs are configured at the SSC switches to create logical groups of endpoints that can communicate as if they were on the same LAN. VLANs also prevent or restrict traffic between endpoints on separate VLANs. However, some environments might not support VLANs. To disable VLAN operation for the Sun Fire B10p SSL proxy blade, use the `set vlan filter disable` command from the CLI interface.

If you choose to use VLANs, refer to the *Sun Fire B10n Content Load Balancing Blade Administration Guide* for detailed information.

---

## Hardware and Software Requirements

Before using the Sun Fire B10n blade, ensure your system meets the hardware and software requirements listed in TABLE 3. If you need a server module for a later operating system release check the Sun Download Center at:

<http://www.sun.com/software/download/network.html>

**TABLE 3** Hardware and Software Requirements

Hardware and Software	Requirements
Hardware	<ul style="list-style-type: none"><li>• Sun Fire™ B10n content load balancing blade</li><li>• Sun Fire B10p SSL proxy blade (optional)</li><li>• Sun Fire B1600 blade system chassis</li><li>• Sun Fire B100s blade server for SPARC or Sun Fire B100x/B200x blade servers for x86</li><li>• Sun Fire V60/V65 and V210/V240 Servers (External to B1600 Chassis)</li></ul>
Software	<ul style="list-style-type: none"><li>• Sun Fire B10n content load balancing blade application software 1.3.5 or subsequent compatible version</li><li>• Sun Fire B10n content load balancing blade BSC (blade support control) firmware v5.1.4* or subsequent compatible version</li><li>• Sun Fire B100s Solaris Operating System versions:<ul style="list-style-type: none"><li>Solaris 8 HW 12/02</li><li>Solaris 8 HW 5/03</li><li>Solaris 8 HW 7/03</li><li>Solaris 8 HW 2/04</li><li>Solaris 9 8/03</li><li>Solaris 9 12/03</li><li>Solaris 9 4/04</li></ul></li><li>• Sun Fire V210/V240 Operating System versions:<ul style="list-style-type: none"><li>Solaris 8 HW 12/02</li><li>Solaris 8 HW 5/03</li><li>Solaris 8 HW 7/03</li><li>Solaris 8 HW 2/04</li><li>Solaris 9 8/03</li><li>Solaris 9 12/03</li><li>Solaris 9 4/04</li></ul></li><li>• Sun Fire B100x/B200x Operating System versions:<ul style="list-style-type: none"><li>x86 Solaris 9 12/03</li><li>x86 Solaris 9 8/03</li><li>x86 Solaris 9 4/04</li><li>Red Hat Enterprise Linux (RHEL) Advanced Server 2.1</li><li>Red Hat Enterprise Linux (RHEL) Advanced Server 2.1 Update 2</li><li>Red Hat Enterprise Linux (RHEL) Advanced Server 3.0</li></ul></li></ul>

**TABLE 3** Hardware and Software Requirements (*Continued*)

Hardware and Software	Requirements
Software ( <i>Continued</i> )	<ul style="list-style-type: none"><li>• Sun Fire V60/V65 Operating System versions: Solaris 9 8/03 Solaris 9 12/03 Solaris 9 4/04 Red Hat Enterprise Linux (RHEL) Advanced Server 2.1 Update 2 Red Hat Enterprise Linux (RHEL) Advanced Server 3.0</li><li>• Sun Fire B1600 SC (system controller) 1.2 or subsequent compatible system controller firmware</li><li>• B10n Solaris server module version v1.65 for Solaris, or B10n Linux server module version xxx1.41-1 for Red Hat Enterprise Linux Advanced Server 2.1.**</li><li>• Sun GigaSwift Ethernet Adapter Patch ID 111883-18 or subsequent compatible patch for supported versions of the Solaris 8 software. Sun GigaSwift Ethernet Adapter Patch ID 112817-10 or subsequent compatible patch for supported versions of the Solaris 9 software.**</li><li>• Sun Ethernet VLAN Patch ID 112119-04 or subsequent compatible patch for supported versions of the Solaris 8 software. Sun Ethernet VLAN Patch ID 114600-02 or subsequent compatible patch supported versions of the Solaris 9 software.***</li></ul>

\* The version number displayed from the `showplatform -v` command from the Sun Fire B1600 SC CLI printout refers to the BSC firmware version. The application software version is observed using the console `show version` command.

\*\*Verify that you are using the supported Linux server module (xxx1.41-1) for the OS version on your Linux server.

\*\*\*The patch currently installed can be displayed by entering `/usr/ccs/bin/mcs -p /platform/sun4u/kernel/drv/ce`. You can download patches from <http://sunsolve.sun.com>

---

## Updating the B1600 System Controller

You can download the latest version of the `sc` firmware from the following web site:

<http://www.sun.com/software/download/network.html>

You need to set up a TFTP boot server to update the `sc` firmware. See the “Setting up a TFTP Server” section of the *Sun Fire B10n Content Load Balancing Blade Administration Guide*.

You can access all the Sun Fire B1600 documentation from the following web site:

[http://www.sun.com/products-n-solutions/hardware/docs/Servers/Workgroup\\_Servers/Sun\\_Fire\\_b100s/index.html](http://www.sun.com/products-n-solutions/hardware/docs/Servers/Workgroup_Servers/Sun_Fire_b100s/index.html)

## ▼ To Update the System Controller Firmware

1. At the `sc` prompt, enter the following command:

```
sc> flashupdate -s install server -f path SSCn/SC.
```

In the following example, 10.4.128.25 is the IP address for your TFTP boot server and `stiletto.1.1/c8/SunFireB1600-sc-v1.1.6.flashSSC0/SC` is the path to the file:

```
sc> flashupdate -s 10.4.128.25 -f stiletto.1.1/c8/SunFireB1600-sc-v1.1.6.flash
SSC0/SC
Warning: Are you sure you want to flashupdate the SSC0/SC flash image (y/n)? y
SSC0/SC: Preparing to flashupdate.
flashupdate: erasing segment 36 programming address ffedffff
SSC0/SC: flashupdate complete.
```

2. Reset the system using `resetsc` to load the new image.

---

## Updating B10n Application Software and BSC Firmware

It is important to verify that you have the latest software for the Sun Fire B10n content load balancing blade. Check the following web site for the latest software and documentation:

<http://www.sun.com/software/download/network.html>

You need to set up a TFTP boot server to update the `sc` firmware. See the “Setting up a TFTP Server” section of the *Sun Fire B10n Content Load Balancing Blade Administration Guide*.

You also need to configure the management IP address and default gateway address. Refer to the “Configuring the Networking” section of the *Sun Fire B10n Content Load Balancing Blade Administration Guide*.



---

**Note** – If you are updating both the B10n application software and BSC firmware, be sure to update the B10n application software *first*.

---

## ▼ To Update the B10n Application Software

With the B10n blade in the booted and running state perform the following steps:

1. **Access the Sun Fire B10n console. At the Sun Fire B1600 SC console SC> type:**

```
sc> console sn
```

Where *n* is the slot number of the B10n blade

2. **Login to the B10n console.**

```
Login: admin  
passwd: admin
```

### 3. Verify the boot image and versions:

```
puma{admin}# show system

Boot Options:
=====
Config Type   Config File   Boot Image   Diag Level   Verbose Mode
-----
running       2             1 (1.2.3)    0             0
next          2             1 (1.2.3)    0             0
0=====

Image Information Table:
=====
Image  Blade  Image Type   Version   Build Date:Time  Size
-----
1      B10n   Load Balancer  1.2.3    12/05/03 : 14:53  4046868
2      B10n   Load Balancer  1.2.2    11/26/03 : 12:15  4045472
diag   B10n   Diagnostics    1.1.9    10/16/03 : 15:36  2410733
=====

Flash FS /RFA0 free space = 13,033,472 bytes

puma{admin}#
```

The B10n software can be loaded with three different images and booted. The three images are image 1, image 2, and diag. These images denote software versions.

To load to image location 1, the blade expects image *filename* to be available in the TFTP server. Where *filename* is `sunfire_b10n.1.3.5`

4. Determine which image to update (image 1 or 2), and update the empty or oldest image.
5. Update the B10n application software

```
puma{admin}# update image
```

You can upgrade the software either interactively or noninteractively.

## ▼ To Update the Software Non-interactively

- As admin, type the following command:

```
puma{admin}# update image tftp server file image_name image location
```

The following image uses the TFTP server with the IP address of 192.50.50.201, the image name of sunfire\_b10n.1.3.5, and the image at location 1.

```
puma{admin}# update image 192.50.50.201 file sunfire_b10n.1.3.5  
image 1
```

The system returns the following output, verifying the parameters entered:

```
file exist! will overwrite /RFA0/BOOTIMAGE/boot_image_1  
Start downloading sunfire_b10n.1.3.5... using TFTP  
Transferring and writing to file /RFA0/BOOTIMAGE/boot_image_1...  
please wait.  
  
puma{admin}#
```

The following image uses the TFTP server with the IP address of 192.50.50.201, the image name of sunfire\_b10n.1.3.5, and the image at location diag.

```
puma{admin}# update image 192.50.50.201 file sunfire_b10n.1.3.5  
image diag
```

The system returns the following output, verifying the parameters entered:

```
file exist! will overwrite /RFA0/BOOTIMAGE/boot_image_diag  
Start downloading sunfire_b10n.1.2.2_diag... using TFTP  
Transferring and writing to file /RFA0/BOOTIMAGE/boot_image_diag  
.....  
please wait.  
  
puma{admin}#
```

See the “To Update the Software Interactively” section of the *Sun Fire B10n Content Load Balancing Blade Version Administration Guide*.

## ▼ To Set the New Image to be the Default Image

1. **Configure the desired Boot Image. At the B10n console type:**

```
puma{admin}# config boot image x
```

Where *x* is the image you just updated

2. **Save the updated image using the commit command:**

```
puma{admin}# commit
commit : Are you sure to continue? [yes|no] yes
```

3. **Reboot to activate the new image:**

```
puma{admin} reboot
reboot: Are you sure to continue? [yes|no] yes
```

## ▼ To Update the BSC Firmware

1. **Escape to the system controller console by typing the pound sign (#) and period (.) in rapid succession:**

```
puma{admin} #.
```

---

**Note** – If the two characters are not typed in rapid succession nothing happens.

---

2. **At the sc prompt, check the current version of the BSC firmware:**

```
sc> showsc -v
FRU      Software Version                Software Release Date
-----
S0       v5.1.1.4-SUNW,B10n,NetBlade1    Aug 12 2003 15:31:48
```

3. At the `sc` prompt, enter the following command:

```
sc> flashupdate -s TFTP_ip-addr -f filename sn
```

Where *TFTP\_ip-addr* is the TFTP server IP address, *n* is the slot number, *filename* is the file name of the image

In the following example, 192.50.50.201 is the IP address for your TFTP boot server and `/tftpboot/525-2018-05-t2.a37`:

```
sc> flashupdate -s 192.50.50.201. -f /tftpboot/525-2018-05-t2.a37 s12
```

4. Reset the system issuing `reset s12` to load the new image.

---

## Replacing Your B10n Blade

The upgraded B10n blade has the following features:

1. The 1.0 BSC firmware
2. Two B10n boot images—version 1.0.1 and 1.1. The default boot image is 1.1.
3. The B10n bootrom, version 1.1.

### ▼ To Export the Configuration From the Old Board

1. Go to the `/RFA0` directory

```
puma{admin}# cd /
```

2. Tar the `CONFIG` directory:

```
puma{admin}# tar lbconfig.tar CONFIG
```

### 3. Export the config tar file:

```
puma{admin}# export file
The FTP server address: <ftp_server_ip>
The source directory path: type [cr] to use current directory:
  (null) source path, using current directory
  The source file name: lbconfig.tar
  The destination directory path: <path_on_ftp_server>
The destination file name: lbconfig.tar
  The user name: <user_name_for_ftp_server>
The user password: <user_password_for_ftp_server>
export file succeed!
```

## ▼ To Import the Configuration to the Upgraded Board

### 1. Power off the old board and remove it from the chassis.

### 2. Install the upgraded board.

The board comes up with an empty configuration with the B10n 1.1 application image running.

### 3. Configure the network interface. Optionally, configure the management VLAN (if applicable).

### 4. Go to the /RFA0 directory:

```
puma{admin}# cd /
```

## 5. Import the 1.0 or 1.1 configuration:

```
puma{admin}# import file
  The FTP server address: <ftp_server_ip>
The source directory path: <path_on_ftp_server>
The source file name: lbconfig.tar
  The destination directory path:
  (null) path, using current directory...
  The destination file name: lbconfig.tar
  The user name: <user_name_for_ftp_server>
The user password: <user_password_for_ftp_server>

import file succeed!
```

## 6. Untar the configuration file.

```
puma{admin}# untar lbconfig.tar
```

## 7. Reboot the B10n blade to get the imported configuration:

```
puma{admin}# reboot
```

---

**Note** – To run traffic with B10n 1.3.5 application image, the blade server module has to be updated to version 1.3.5.

---

---

# Updating Your Server

Use the appropriate instructions for updating your Solaris or Linux servers.

## ▼ To Update the SPARC Solaris Server Module

### 1. Download the 1.3.5 version of the server module software from the following site:

<http://www.sun.com/software/download/network.html>

**2. Unzip the file:**

```
# /usr/bin/unzip SunFire_B10n-1_2_Update-SolarisModule.zip
```

**3. Install the SPARC Solaris server module software packages:**

```
# cd path_to_unzipped_file/Solaris/sparc  
# pkgadd -d .
```

**4. Restart the Solaris server module:**

```
# /etc/init.d/clbctl stop  
# /etc/init.d/clbctl start
```

## ▼ To Update the x86 Solaris Server Module

**1. Download the 1.3.5 version of the server module software from the following site:**

<http://www.sun.com/software/download/network.html>

**2. Unzip the file:**

```
# /usr/bin/unzip SunFire_B10n-1_2_Update-SolarisModule.zip
```

**3. Install the x86 Solaris server module software packages:**

```
# cd path_to_unzipped_file/Solaris/i386  
# pkgadd -d .
```

**4. Restart the Solaris server module:**

```
# /etc/init.d/clbctl stop  
# /etc/init.d/clbctl start
```



## ▼ To Update the Linux Server Module

1. Download the 1.3.5 version of the server module software from the following site:  
<http://www.sun.com/software/download/network.html>

2. Unzip the file:

```
# /usr/bin/unzip SunFire_B10n-1_2_Update-LinuxModule.zip
```

Different Linux OS subdirectories are available, such as, RHAS\_2.1, SLES\_8.0, ... additionally, hardware platforms such as B100x, B200x and V60\_65x are available.

3. Install the Linux server module for RHAS 2.1 Update 2, for example:

```
# rpm -i sun-clb-k2_4_9_e_24-1.41-1.i386.rpm  
# rpm -i sun-clb-admin-1.41-1.i386.rpm
```

4. Restart the Linux server module:

```
# /etc/init.d/sun-clb restart
```

## ▼ To Upgrade the Linux Server Module From an Existing Installation

1. Download the 1.3.5 version of the server module software from the following site:  
<http://www.sun.com/software/download/network.html>

2. Unzip the file:

```
# /usr/bin/unzip SunFire_B10n-1_2_Update-LinuxModule.zip
```

Different Linux OS subdirectories are available, such as, RHAS\_2.1, SLES\_8.0, ... additionally, hardware platforms such as B100x, B200x and V60\_65x are available.

3. Upgrade the Linux server module for RHAS 2.1 Update 2, for example:

```
# rpm -U sun-clb-k2_4_9_e_24-1.41-1.i386.rpm  
# rpm -U sun-clb-admin-1.41-1.i386.rpm
```

#### 4. Restart the Linux server module:

```
# /etc/init.d/sun-clb restart
```

---

## Known Issues

This section outlines the known problems with the current version of the software and describes workarounds to overcome these problems.

### Stopping Failover Monitoring or Unknown Failover State (Bug ID 5046437 and Bug ID 4925823)

When failover monitoring is stopped and the configuration is committed and then the system is rebooted it could come up without any of the load balancing configuration loaded. It could also happen if you skip the failover synchronization at boot time.

Work around:

1. **The configured failover peer and the B10n in consideration should not come up with the same load balancing configuration when failover is stopped. To prevent them from coming up with the same configuration turnoff the peer or erase the configuration on the peer (config erase config-files) and reboot.**
2. Enter `show system` to find out what configuration file you are using, which is displayed in the second column. In this example, the config file is `config_x`, where `x` is 1 or 2.
3. Remove two failover configuration files:

```
puma{admin}# rm /RFA0/config/failover/config_1/failover/failover_cmd.conf  
puma{admin}# rm /RFA0/config/failover/config_1/failover.state
```

4. Reboot the B10n blade.

## Stopping an Application Server While Running Application Monitoring (Bug ID 4997595)

If an application is reported as down (from application monitoring) on a B10n and when the application is down, if the application monitoring is disabled then when the server application comes back up this is not detected and traffic is not sent to that server for that service.

Workaround: Either enable application monitoring again or remove the server from the service completely (that is, from all the groups in the service) and then add it again to the service.

## Unknown Filter Edge [b9000010] (Bug ID 4925821)

The B10n blade can hang up on boot after displaying the following message:

```
Unknown Filter Edge
```

This does not happen in normal operation. It happens only if the `classifier.pm` file gets corrupted in the `config/config_X` directory. Where `X` is the current configuration (1 or 2).

Workaround: Boot using the alternate configuration and remove the file `config/config_X/classifier.pm` where `X` is the configuration boot up that fails and has a value of 1 or 2.

## VIP Address Conflict (Bug ID 4910001)

If the load balancer VIP address is mistakenly used on another device, the other device broadcasts a gratuitous ARP and forces all of the clients and routers to learn that ARP entry.

Use the `config vip-broadcast VIP-address mask` command to force the load balancer to send a gratuitous ARP and force the clients and routers to relearn the VIP ARP entry as that of the load balancer.

## Configuring VIP Addresses to be the Same as path failover Target IP Address (Bug ID 4907833)

This problem indicates a bad network configuration. The VIP address cannot be the same as the `path failover` target IP address. A future release will check for this condition.

## Layer 7 Based Services and Layer 4 Services With Rules Will Fail to Respond (Bug ID 4998054 and Bug ID 5060108)

This error occurs rarely and only when the system is rebooted. The message on the console is as follows:

```
SPI3 IF not responding (powercycle the blade to recover)
```

Powercycle the B10n blade only if it prints out this message continuously every minute. To powercycle the system go to the B1600 platform console and enter `poweroff` to turn off the system and then enter `poweron` to turn it on. Just entering `reboot` on the B10n console does not solve the problem, the system must be powercycled.

## Removing Services (Bug ID 5057931)

Removing all of the load balancing services and then entering `commit` does not remove the services from the files. The services will be loaded when the system is rebooted. Removing some of the services works correctly.

Workaround: Remove the services first and then remove the configuration file and enter `commit` to commit the changes. Use the following procedure:

1. Enter `show system` to verify what configuration file you are using, which is displayed in the second column. In this example, the `config` file is `config_x` where `x` is 1 or 2.

2. Remove the `/RFA0/config/config_X/service/services.conf` file where 'X' is 1 or 2:

```
puma{admin}# rm /RFA0/config/config_X/service/services.conf
```

## CRITICAL Message Displayed When Removing a Service (Bug ID 5057951)

The following message is not a critical message and just notifies that the service is going away.

```
CRITICAL: No valid servers in default group: Deactivating service  
<servicename>
```

Ignore this message.

## Rule Build Required Message (Bug ID 5057959)

When committing changes, the system reports that a rule build is required when there are no services in the system.

The message is as follows:

```
The Rule Classifier is not saved. Rule build required.
```

Ignore this message.

## Rule Build Complete Message Appears Only on the Console (Bug ID 4879355)

When the rule build process is complete, the message appears only on the console and not on the Telnet sessions.

Workaround: Enter the `show build status` command to verify if it is complete.

## Message Indicates Configuration Change After Rebooting (Bug ID 5043929)

When a B10n blade is rebooted, a message reports that the configuration has changed even if rebooted immediately after entering `commit`.

This error occurs rarely. For safety, ensure all the changes are committed before entering `reboot`.

## Using the `poweroff` and `poweron` Commands (Bug ID 5028523)

The B10n blade may fail to complete the booting process if no messages are being displayed on the console. Use the `showplatform -v` command to check for OS running status.

Workaround: Enter a `poweroff` command followed by a `poweron` command to restart the booting process.

## Using the `app-monitor` Configuration Command (Bug ID 4997604)

Using the `app-monitor` configuration command with missing parameters (`interval` & `max-try`) returns an incorrect error message. For example, the following error message occurs:

```
puma{admin}# config service app-monitor name ssl4 proto http
Error: Invalid parameter.
```

To be more accurate, it should display "Error: Missing parameter."

## Time Not Kept Consistent With System Controller (SC) (Bug ID 4946746)

After rebooting the B10n blade, the time might be out of sync with the SC.

Workaround: Reboot the B10n blade to resynchronize the clocks.

## Incorrect MAC Address Overwritten Message (Bug ID 4925709)

A message similar to the following could appear on the B10n console of both the active and standby blades.

```
0x8f5fc2b0 (tNetTask): arp info overwritten for c0a865ab by 00:03:ba:2a:05:60
```

The MAC addresses are not changed and no conflicts are caused in the network. The message displays the correct MAC address for the right server IP address.

## Diag Back-To-Back(External) LoopBack Test (Bug ID 4928957)

This test passes with or without cable, but should only pass with a valid cable connected.

## Disabling All VLANs (Bug ID 4886383)

In the command-line interface (CLI), the **config no enable vlan all** command only disables the Data and Management VLANs and not the Service VLAN.

## Configuring Path-failover IP Addresses (Bug ID 4908470)

The failover active peer incorrectly allows configuring the path-failover IP address to be the same as the standby interface address. If this scenario is committed or failover is forced to the standby peer, the path-failover configuration information will not be transmitted. Consequently, when the standby becomes active, it will not have the path-failover configuration information.

## Building Rules (Bug ID 4925705)

Building rules twice deletes the rule build status information. If rules are built without making any changes, it finishes up immediately, which resets the counters in the `show build status` output.

## Error Messages for Updating the Bootrom Image (Bug ID 4926343)

If a non-bootrom image is mistakenly updated in flash with the `update image` command, the following error message is displayed: "Bootrom image version is old." This error message should indicate that a non-bootrom image is not acceptable in flash.

## Older Date Appears on `config_1` and `config_2` Files (Bug ID 4973992)

Jan 1 1980 date appears as the date for the `config_1` and `config_2` configuration files. This date is incorrect.

## Application Monitor Commands (Bug ID 5003231)

The application monitor command parameters require the entire command to be typed even if only one parameter is being changed. For example, just changing the interval or max-try parameters requires the following syntax:

```
puma{admin}# conf service app-monitor name name interval num max-try num proto http
```

## SSL Traffic Without an SSL Device Cannot be Layer 7 Load Balanced (Bug ID 4950182)

In the absence of an SSL device, SSL traffic can only be Layer 4 load balanced as there is no way to look at the Layer 7 data and load balanced on that basis.



## IP Persistence Does Not Release Its Persistence With Short Timeouts (Bug ID 5023896)

Short timeout values do not have the expected result. Timeout values must be at least 15–20 minutes, and the granularity of timing out entries is in the order of 10 minutes.

## Output From the show arp Command (Bug ID 4819914)

The following example shows a typical output from the show arp command:

LINK LEVEL ARP TABLE					
destination	gateway	flags	Refcnt	Use	Interface
192.50.50.11	00:03:af:26:73:07405	0	35330		iq0
192.50.50.12	00:03:af:26:97:fb405	1	16653		iq0

In the ARP table the gateway and flags columns are improperly shown. In the example above, 405 in the first line should be aligned under the flags heading.

## Online Help Documentation Error (Bug ID 4900728)

Due to errors in Wind River's Rapid Control software, the following commands print the same output:

- config no dns ? and config dns ?
- config no service ? and config service ?
- config no ssl ? and config ssl ?
- config no path-failover ? and config path-failover ?

In addition, the correct syntax for these "config no" commands is as follows:

```
puma{admin}# config remove dns server ip-addr
puma{admin}# config remove service service-name
puma{admin}# config remove ssl
puma{admin}# config remove path-failover
```

## Specific Sequence Required

System may panic if the content load balancing module (clbmod) is added to a “down” ce interface

Workaround: Be sure the ce interface is “up” before you load clbmod.

---

**Note** – If the B10n software from the Solaris 8 7/03 Software Supplement CD is loaded onto an unsupported platform and the system is rebooted, the following message is displayed: “can’t load module: No such file or directory.”

---

## Adding an SSL Service With a Duplicate Port (Bug ID 4908515)

When adding an SSL service, using the same VIP address with a different port, but the same SSL port is not allowed. The new SSL service must have a unique port number. For example, if an initial SSL service is running on SSL port 880, you must specify a different SSL port number for each new SSL service such as SSL port 881, 882, and so on.

Workaround: Remove the failover configuration from the system with the following commands as admin in config mode:

```
puma(config){admin}# config remove failover
puma(config){admin}# rm /RFA0/config/failover/config_x/failover/
failover_cmd.conf
```

Reboot the system.

If you still want to keep the blade failover configuration after the reboot, please refer to the “Configuring Failover” chapter in the *Sun Fire B10n Content Load Balancing Blade Version Administration Guide*.

---

**Note** – In all of the references to config\_x, the ‘x’ is 1 or 2 depending on whether your load balancing is currently using configuration directory config\_1 or config\_2.

---

# Skipping the Failover Synchronization at Boot Time

At boot time, you have the option of skipping the blade failover synchronization. During boot the system prints the following message and waits for 5 seconds for you to respond:

```
Press Return key to skip the failover synchronization ...
```

```
config no ip interface 0|1
```

If both interfaces of the B10n device are configured in the same subnet and if one of the interfaces is unconfigured, there might be loss of network connectivity from the B10n device. The device might not be able to switch all servers to the alternate interface. This can cause server/SSL devices to be marked down, and they will not be used in the load balancing.

Workaround: After unconfiguring the interface. Do a commit and then reboot the system.

---

## Troubleshooting

You may notice the following behaviors, which might be interpreted as being problems. However, they are normal behaviors.

### VIP IDs Not Checked

If another system in the subnet is configured with the IP address used in the VIP of a service configured on B10n the networking for that system will not work because the clients and routers will learn one machine's MAC and the other machine will not receive any traffic on that VIP.

Workaround: Because this is normal behavior, the only workaround is to ensure that you do not use duplicate VIP addresses.

## commit Allowed Though No Changes

The B10n software still allows the commit command even though no changes have been made to the configuration.

Workaround: This problem causes no ill effects, so it can be noted and ignored.

## Server/SSL Does Not Respond to ping Even Though it is Marked as Up.

If both interfaces are configured in the same subnet then in some scenarios it is possible that the default route to a server/SSL device might be down and the devices might be unreachable (ping fails) from B10n, but the monitoring shows them as up.

This is not a bug. The monitoring will switch to the alternate interface and try to reach the device. ping will only try the one default interface.