

---

**Important  
information  
concerning  
the SSP Power Patch,  
the 2760A System Board,  
and the 2761A System Board**

---

---

Installation of the following patches is *mandatory* for SSP version 3.0 and SSP version 3.1.

- If using SSP version 3.0, install patch number 104846
- If using SSP version 3.1, install patch number 106465 and 105683.

The revision of these patches may change. Refer to the SunSolve database for the most current version.

Refer to the README file accompanying the patch for installation instructions.



**Caution** – Failure to install these patches will:

- cause possible system component damage when using 2760A system boards and processors that are unsupported by the 2760A system board.
  - preclude the 2761A system board from powering on.
  - preclude domains that are using a 2761A system board from properly performing automatic reboots, failure recovery, and processor monitoring.
-

---

## Accessing Sun Documentation Online

A broad selection of Sun system documentation is located at the following web site:

<http://www.sun.com/products-n-solutions/hardware/docs>

To locate the most current documentation at this site, select a product category. The documents at that location may include updated information that did not ship with your product, such as product notes, release notes, late-breaking news, or later revisions of manuals.

A complete set of Solaris documentation and many other titles are located at:

<http://docs.sun.com>

## Ordering Sun Documentation

Fatbrain.com, an Internet professional bookstore, stocks select product documentation from Sun Microsystems, Inc. For a list of documents and how to order them, visit the Sun Documentation Center on Fatbrain.com at:

<http://www.fatbrain.com/documentation/sun>

## Sun Welcomes Your Comments

Sun is interested in improving its documentation and welcomes your comments and suggestions. You can email your comments to Sun at:


[docfeedback@sun.com](mailto:docfeedback@sun.com)

Please include the part number (805-7188-11) of the document in the subject line of your email.

Copyright 1998 Sun Microsystems, Inc. All rights reserved. Use is subject to license terms. Third-party software, including font technology, is copyrighted and licensed from Sun suppliers. Sun, Sun Microsystems, the Sun Logo, and Solaris are trademarks or registered trademarks of Sun Microsystems, Inc. in the U.S. and other countries. **RESTRICTED RIGHTS:** Use, duplication, or disclosure by the U.S. Government is subject to restrictions of FAR 52.227-14(g)(2)(6/87) and FAR 52.227-19(6/87), or DFAR 252.227-7015(b)(6/95) and DFAR fs227.7202-3(a).

Copyright 1998 Sun Microsystems, Inc. Tous droits réservés. Distribué par des licences qui en restreignent l'utilisation. Le logiciel détenu par des tiers, et qui comprend la technologie relative aux polices de caractères, est protégé par un copyright et licencié par des fournisseurs de Sun. Sun, Sun Microsystems, le logo Sun, et Solaris sont des marques de fabrique ou des marques déposées de Sun Microsystems, Inc. aux Etats-Unis et dans d'autres pays.

Please Recycle Sun Microsystems, Inc. • 901 San Antonio Road • Palo Alto, CA 94303-4900  
USA • 650 960-1300 • Fax 650 969-9131



Part Number: 805-7188-11  
December 1998, Revision A



---

# Sun™ Enterprise™ 10000 System Power Patch Note

**Important Notice**

